

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	Height (m)	DIMENSIONS						Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T1	1	<i>Tilia cordata</i> Small leaved lime	13.0	59	1	7.0	6.5	7.0	7.5	3.5	Early Mature	Structural condition Good. Physiological condition Good. Ivy or climbing plant. Crown to ground level		157.5	7.1	40+	B2
Tree T2	1	<i>Quercus robur</i> English oak	12.0	52	1	3.5	5.5	4.5	5.0	4.5	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Restricted / obscured. Crown conflict - Structure / boundary / wire / tree. Ivy or climbing plant. Unable to inspect tree(s) closely due to ivy/climbing plant(s). Telephone and Electricity cables within crown Growing within hedgerow		122.3	6.2	40+	B2
Tree T3	1	<i>Fagus sylvatica f. purpurea</i>	15.0	75	1	8.6	8.9	7.0	7.2	2.5	Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Epicormic growth - Base. Epicormic growth from rootstock impeding thorough inspection		254.5	9.0	40+	A1
Tree T4	1	<i>Tilia cordata</i> Small leaved lime	17.0	64	1	5.7	6.1	6.0	6.6	4.0	Mature	Structural condition Good. Physiological condition Good. Ivy or climbing plant. Crown to ground level Minor Ivy clad stem		185.3	7.7	40+	A2
Tree T5	1	<i>Quercus robur</i> English oak	15.0	68	1	8.5	8.1	8.0	8.9	2.5	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Restricted / obscured. Decline - Suspected. Ivy or climbing plant. Deadwood - Major. Unable to inspect tree(s) closely due to ivy/climbing plant(s).		209.2	8.2	40+	B3
Tree T6	1	<i>Quercus robur</i> English oak	17.0	79	1	7.1	9.0	8.0	8.1	3.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Restricted / obscured. Decline - Suspected. Ivy or climbing plant. Deadwood - Major. Bark wound - Physical damage or vandalism. Unable to inspect tree(s) closely due to ivy/climbing plant(s).		282.3	9.5	40+	B3
Tree T7	1	<i>Tilia cordata</i> Small leaved lime	17.0	62	1	8.0	7.8	7.1	8.3	3.5	Mature	Structural condition Good. Physiological condition Good. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Heavily Ivy clad stem Crown to ground level Unable to inspect tree(s) closely due to ivy/climbing plant(s).		173.9	7.4	40+	B2
Tree T8	1	<i>Tilia cordata</i> Small leaved lime	12.0	47	1	4.1	4.2	4.0	4.0	3.0	Mature	Structural condition Good. Physiological condition Good. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Heavily Ivy clad stem Crown to ground level Unable to inspect tree(s) closely due to ivy/climbing plant(s).		99.9	5.6	40+	B2

Stem **green** estimated valueStem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T9	1 <i>Quercus robur</i> English oak	8.0	45	1	8.2	1.0	0.0	3.9	2.5	Mature	Structural condition Fair. Physiological condition Good. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Unbalanced crown - Major. Heavily Ivy clad stem Heavily biased crown North Unable to inspect tree(s) closely due to ivy/climbing plant(s).		91.6	5.4	40+	C3
Tree T10	1 <i>Fagus sylvatica f. purpurea</i>	13.0	36	1	5.6	4.8	5.7	6.5	2.0	Early Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		58.6	4.3	40+	B1
Tree T11	1 <i>Fraxinus excelsior</i> Ash	12.0	16	1	2.1	2.3	3.8	4.2	3.0	Young	Structural condition Good. Physiological condition Good. Fork - Suspected structurally sound.		11.6	1.9	20-40	C2
Tree T12	1 <i>Betula pendula</i> Silver birch	14.0	20	1	1.6	2.0	3.6	2.0	6.0	Semi Mature	Structural condition Good. Physiological condition Good. Bark wound - Physical damage or vandalism.		18.1	2.4	20-40	C2
Group G13	14 <i>Salix caprea</i> Goat willow 5 <i>Prunus spinosa</i> Blackthorn 5 <i>Betula pendula</i> Silver birch	12.0	23						1.5	Semi Mature	Structural condition Fair. Physiological condition Fair. Multi-stemmed. Natural regeneration. Mostly multi-stemmed Goat willow Height, spread, tree numbers and DBH estimated for group				10-20	C3
Tree T14	1 <i>Populus nigra 'Italica'</i> Italian black poplar	15.0	44 AVE	2	2.0	2.5	2.0	2.5	2.0	Mature	Structural condition Poor. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Co-dominant. Pollard - Regrown. Pollard points - Structurally suspect. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		156.4	7.1	0-10	U
Tree T15	1 <i>Populus nigra 'Italica'</i> Italian black poplar	17.0	63	1	2.0	2.5	2.0	2.5	5.0	Mature	Structural condition Poor. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Co-dominant. Pollard - Regrown. Leaning trunk - Minor. Pollard points - Structurally suspect. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		179.6	7.6	0-10	U
Tree T16	1 <i>Populus nigra 'Italica'</i> Italian black poplar	19.0	63	1	2.0	2.5	2.0	2.5	2.0	Mature	Structural condition Poor. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Co-dominant. Pollard - Regrown. Leaning trunk - Minor. Pollard points - Structurally suspect. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		179.6	7.6	0-10	U

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category	
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								Crown Clearance (m)
Tree T17	1	<i>Populus nigra 'Italica'</i> Italian black poplar	15.0	31	1	2.0	2.5	2.0	2.5	5.0	Early Mature	Structural condition Poor. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Co-dominant. Pollard - Regrown. Leaning trunk - Minor. Pollard points - Structurally suspect. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		43.5	3.7	0-10	U
Tree T18	1	<i>Fraxinus excelsior</i> Ash	12.0	36	1	6.0	5.7	5.8	6.0	2.5	Early Mature	Structural condition Fair. Physiological condition Good. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Fungal fruiting body - structural decay suspected. Heavily Ivy clad stem Inonotus hispidus fungal fruiting body found on ground next to subject tree, cannot assess crown structure due to dense Ivy coverage. Unable to inspect tree(s) closely due to ivy/climbing plant(s).		58.6	4.3	20-40	C2
Tree T19	1	<i>Quercus robur</i> English oak	12.0	28	1	6.5	4.3	5.9	6.1	0.5	Early Mature	Structural condition Good. Physiological condition Good. Root environment - Restricted. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Located on raised area Heavily Ivy clad stem		35.5	3.4	40+	B1
Tree T20	1	<i>Quercus robur</i> English oak	12.0	34	1	6.5	4.3	4.6	5.8	0.5	Early Mature	Structural condition Good. Physiological condition Good. Root environment - Restricted. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Located on raised area Heavily Ivy clad stem		52.3	4.1	40+	B1
Tree T21	1	<i>Populus nigra 'Italica'</i> Italian black poplar	13.0	62	1	2.0	2.0	2.0	2.0	2.0	Mature	Structural condition Poor. Physiological condition Poor. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Co-dominant. Pollard - Regrown. Pollard points - Structurally suspect. Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s). Dense vegetation obscuring thorough inspection		173.9	7.4	0-10	U
Group G22	15	<i>Ulmus sp.</i> Elm sp.	12.0	11	1	2.0	2.0	2.0	2.0	2.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Altered ground level - Historic. Root environment - Restricted. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Ivy or climbing plant. Height, spread, tree numbers and DBH estimated for group Located on raised area			10-20	C3	
	5	<i>Tilia cordata</i> Small leaved lime															
	5	<i>Prunus spinosa</i> Blackthorn															
	8	<i>Populus nigra</i> Black poplar															

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T23	1 <i>Tilia cordata</i> Small leaved lime	10.0	19	2	3.6	4.0	4.3	4.1	0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Stems - Sub-dominant. Altered ground level - Historic. Heavily Ivy clad stem Located on raised area Unable to inspect tree(s) closely due to ivy/climbing plant(s).		26.5	2.9	20-40	C2
Group G24	8 <i>Ulmus sp.</i> Elm sp. 5 <i>Quercus robur</i> English oak 12 <i>Cerasus avium</i> Wild cherry	9.0	11						0.0	Young	Structural condition Fair. Physiological condition Fair. Height, spread, tree numbers and DBH estimated for group				20-40	C2
Tree T25	1 <i>Taxus baccata</i> Yew	4.0	28	1	3.5	1.8	3.5	2.3	0.0	Semi Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Altered ground level - Historic. Located on raised area		35.5	3.4	40+	C2
Tree T26	1 <i>Ulmus sp.</i> Elm sp.	13.0	12	1	2.6	2.5	2.4	2.2	3.0	Semi Mature	Structural condition Good. Physiological condition Poor. Dutch elm disease. Minor DED at present.		6.5	1.4	0-10	U
Tree T27	1 <i>Pinus sylvestris</i> Scots pine	12.0	38	1	1.0	1.0	3.1	3.0	5.0	Early Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Suppressed crown - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation		65.3	4.6	20-40	B1
Tree T28	1 <i>Quercus robur</i> English oak	15.0	59	1	6.0	6.0	6.0	6.0	2.5	Mature	Structural condition Fair. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Unbalanced crown - Major. Heavily Ivy clad stem Crown spreads estimated due to dense vegetation Unable to inspect tree(s) closely due to ivy/climbing plant(s). Located on other side of chain-link fencing, ownership unclear		157.5	7.1	20-40	B2
Tree T29	1 <i>Prunus insititia</i>	5.0	23	1	3.4	4.3	3.1	3.0	2.0	Mature	Structural condition Fair. Physiological condition Good. Stems - Sub-dominant. Epicormic growth - Base. Ivy or climbing plant. Located on other side of chain-link fencing, ownership unclear		23.9	2.8	10-20	C3
Tree T30	1 <i>Prunus insititia</i>	4.0	8	7	2.2	3.8	4.2	1.8	1.0	Early Mature	Structural condition Fair. Physiological condition Good. Multi-stemmed. Epicormic growth - Base. Ivy or climbing plant. Located on other side of chain-link fencing, ownership unclear		20.3	2.5	10-20	C3

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS								Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T31	1	<i>Fagus sylvatica</i> Beech	19.0	62	1	5.6	4.8	5.7	6.5	3.0	Early Mature	Structural condition Good. Physiological condition Good. Twin-stemmed. Crown difficult to assess due to dense neighbouring vegetation Located on other side of chain-link fencing, ownership unclear		173.9	7.4	40+	A1
Tree T32	1	<i>Pinus sylvestris</i> Scots pine	12.0	34	1	3.0	1.5	3.0	3.0	5.0	Early Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Suppressed crown - Minor. Unbalanced crown - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation		52.3	4.1	20-40	B1
Tree T33	1	<i>Taxus baccata</i> Yew	4.5	24	1	3.6	4.8	4.2	2.3	0.0	Semi Mature	Structural condition Good. Physiological condition Good. Stems - Sub-dominant. Access to inspect base - Restricted / obscured. Altered ground level - Historic. Located on other side of chain-link fencing, ownership unclear		26.1	2.9	40+	C2
Tree T34	1	<i>Fagus sylvatica</i> Beech	17.0	59	1	6.2	6.5	5.7	7.2	2.0	Early Mature	Structural condition Good. Physiological condition Good. Twin-stemmed. Ivy or climbing plant. Crown difficult to assess due to dense neighbouring vegetation Located on other side of chain-link fencing, ownership unclear Ivy clad stem		157.5	7.1	40+	A1
Tree T35	1	<i>Pinus sylvestris</i> Scots pine	14.0	32	1	2.5	2.5	2.5	2.5	4.0	Early Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Suppressed crown - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation		46.3	3.8	40+	B1
Tree T36	1	<i>Quercus robur</i> English oak	15.0	68	1	5.8	10.8	4.0	9.5	2.5	Mature	Structural condition Fair. Physiological condition Fair. Ivy or climbing plant. Access to inspect base - Restricted / obscured. Unbalanced crown - Major. Heavily Ivy clad stem Crown spreads estimated due to dense vegetation Unable to inspect tree(s) closely due to ivy/climbing plant(s). Located on other side of chain-link fencing, ownership unclear		209.2	8.2	20-40	B2
Tree T37	1	<i>Fagus sylvatica</i> Beech	17.0	54	1	7.0	7.6	6.0	7.2	2.0	Early Mature	Structural condition Fair. Physiological condition Good. Reaction wood / Adaptive growth - Stem / stems. Ivy or climbing plant. Crown difficult to assess due to dense neighbouring vegetation Located on other side of chain-link fencing, ownership unclear Ivy clad stem Large burr on North side at 1.5 metres. Approx. 35 x 25cm DBH measured at 1 metre above ground level Crown spreads estimated due to dense vegetation		131.9	6.5	40+	B2

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	Height (m)	Stem diameter (cm)	DIMENSIONS				Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category		
					No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)									Spread W (m)	
Tree T38	1	<i>Pinus sylvestris</i> Scots pine	14.0	34	1	2.5	0.0	2.5	2.5	6.0	Early Mature	Structural condition Good. Physiological condition Good. Unbalanced crown - Minor. Base / stems obscured - Vegetation. Suppressed crown - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation						
Tree T39	1	<i>Pinus sylvestris</i> Scots pine	14.0	34	1	2.5	2.5	2.5	2.5	6.0	Early Mature	Structural condition Good. Physiological condition Good. Base / stems obscured - Vegetation. Suppressed crown - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation						
Tree T40	1	<i>Pinus sylvestris</i> Scots pine	14.0	31	1	2.5	2.5	2.5	2.5	6.0	Early Mature	Structural condition Fair. Physiological condition Good. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Suppressed crown - Minor. Ivy or climbing plant. Leaning trunk - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).						
Tree T41	1	<i>Tilia cordata</i> Small leaved lime	15.0	72	1	6.5	6.5	6.5	6.5	4.0	Early Mature	Structural condition Fair. Physiological condition Good. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Fork - Suspected structurally sound. Twin-stemmed. Crown difficult to assess due to dense neighbouring vegetation Located on other side of chain-link fencing, ownership unclear Crown spreads estimated due to dense vegetation Dense vegetation obscuring thorough inspection						
Tree T42	1	<i>Pinus sylvestris</i> Scots pine	10.0	28	1	4.5	3.0	1.5	2.0	5.0	Early Mature	Structural condition Fair. Physiological condition Good. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Suppressed crown - Minor. Ivy or climbing plant. Leaning trunk - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).						

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS					Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T43	1 <i>Pinus sylvestris</i> Scots pine	14.0	33	1	5.0	3.0	0.5	1.5	6.0	Early Mature	Structural condition Fair. Physiological condition Good. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Unbalanced crown - Major. Ivy or climbing plant. Leaning trunk - Minor. Located on other side of chain-link fencing, ownership unclear Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation Heavily Ivy clad stem Unable to inspect tree(s) closely due to ivy/climbing plant(s).		49.3	4.0	20-40	B1
Tree T44	1 <i>Fagus sylvatica</i> Beech	15.0	53	1	7.0	7.0	7.0	7.0	2.0	Mature	Structural condition Fair. Physiological condition Good. Access to inspect base - Not possible. Ivy or climbing plant. Base / stems obscured - Vegetation. Crown difficult to assess due to dense neighbouring vegetation Located on other side of chain-link fencing, ownership unclear Heavily Ivy clad stem Crown spreads estimated due to dense vegetation Suppressed inner crown		127.1	6.4	40+	B2
Group G45	25 <i>Ulmus sp.</i> Elm sp. 5 <i>Quercus robur</i> English oak 15 <i>Prunus spinosa</i> Blackthorn 20 <i>Laurocerasus officinalis</i> Cherry Laurel 15 <i>Ilex aquifolium</i> Holly 15 <i>Crataegus monogyna</i> Common hawthorn 20 <i>Buxus sempervirens</i> Common box	10.0	12						0.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group Located on other side of chain-link fence Good screen from highway Dense understory vegetation				10-20	C2
Group G46	85 <i>Quercus robur</i> English oak 5 <i>Crataegus monogyna</i> Common hawthorn	4.0	7						0.5	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Height, spread, tree numbers and DBH estimated for group Mostly open grown, young Oak trees				40+	C1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)							
Hedge H47	18	<i>Fagus sylvatica</i> Beech	8.0	20					1.0	Early Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Neglected / overgrown. Informal hedgerow, good screen from neighbouring development Height, spread, tree numbers and DBH estimated for group Previously topped at 1 metre above ground level			20-40	B2	
Group G48	8	<i>Tilia cordata</i> Small leaved lime	14.0	32					4.0	Early Mature	Structural condition Fair. Physiological condition Fair. Epicormic growth - Bole / principal stems. Access to inspect base - Not possible. Height, spread and DBH estimated for group Trees located on adjacent land, stems < 1 metre from boundary			40+	B2	
Group G49	35	<i>Quercus robur</i> English oak	4.0	7					0.5	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Height, spread, tree numbers and DBH estimated for group Mostly open grown, young Oak trees			40+	C1	
Hedge H50	30	<i>Laurocerasus officinalis</i> Cherry Laurel	2.5	8					0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Maintained. Access to inspect base - Not possible. Hedge located on adjacent land, stems < 1 metre from boundary Height, spread, tree numbers and DBH estimated for group			10-20	C2	
Group G51	1 40	<i>Quercus robur</i> English oak <i>Prunus spinosa</i> Blackthorn	3.5	3					0.0	Young	Structural condition Fair. Physiological condition Fair. Natural regeneration. Height, spread, tree numbers and DBH estimated for group			10-20	C3	
Tree T52	1	<i>Prunus domestica</i> Plum	4.0	8	1	2.5	2.5	2.5	2.5	2.0	Young	Structural condition Good. Physiological condition Fair. Crown spreads estimated Located on adjacent property, < 1 metre from boundary	2.9	1.0	20-40	C1
Tree T53	1	<i>Quercus robur</i> English oak	6.0	26	1	4.0	4.2	4.8	4.4	2.5	Semi Mature	Structural condition Good. Physiological condition Good. Northern crown spread estimated	30.6	3.1	40+	B1
Hedge H54	25 25 50	<i>Prunus spinosa</i> Blackthorn <i>Fagus sylvatica</i> Beech <i>Crataegus monogyna</i> Common hawthorn	1.5	5					0.0	Semi Mature	Structural condition Good. Physiological condition Good. Hedgerow - Maintained. Located on adjacent property Tree numbers and DBH estimated for group			10-20	C2	

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS								Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T55	1	<i>Quercus robur</i> English oak	14.0	68	1	9.8	7.9	8.2	7.5	2.5	Mature	Structural condition Good. Physiological condition Good. Deadwood - Major. Crown to ground level Deadwood present believed to not be a significant risk to targets		209.2	8.2	40+	B2
Tree T56	1	<i>Betula pendula</i> Silver birch	10.0	22	1	4.1	4.6	2.2	2.8	1.5	Semi Mature	Structural condition Good. Physiological condition Good. Leaning trunk - Minor. Crown to ground level		21.9	2.6	40+	B2
Tree T57	1	<i>Quercus robur</i> English oak	16.0	58	1	7.8	7.9	8.2	7.4	3.0	Mature	Structural condition Fair. Physiological condition Good. Deadwood - Major. Epicormic growth - Bole / principal stems. Crown to ground level Deadwood present believed to not be a significant risk to targets		152.2	7.0	40+	B2
Tree T58	1	<i>Quercus robur</i> English oak	11.0	25	1	5.2	4.1	4.2	4.2	1.5	Mature	Structural condition Good. Physiological condition Good. Stems - Sub-dominant. Ivy clad stem		28.3	3.0	40+	B1
Tree T59	1	<i>Salix x sepulcralis</i>	7.0	47	1	6.1	5.9	4.4	5.2	3.0	Early Mature	Structural condition Fair. Physiological condition Fair. Crown reduction - Recent. Large pruning wounds		99.9	5.6	20-40	C1
Tree T60	1	<i>Quercus robur</i> English oak	15.0	65	1	9.1	8.0	7.6	6.2	3.0	Mature	Structural condition Good. Physiological condition Good. Deadwood - Major. Crown to ground level Deadwood present believed to not be a significant risk to targets		191.1	7.8	40+	A1
Tree T61	1	<i>Populus nigra 'Italica'</i> Italian black poplar	15.0	48	1	1.0	1.5	2.8	1.0	1.5	Early Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems.		104.2	5.8	10-20	C2
Tree T62	1	<i>Populus nigra 'Italica'</i> Italian black poplar	15.0	58	1	2.4	2.6	3.0	2.5	1.5	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems.		152.2	7.0	10-20	C2
Tree T63	1	<i>Populus nigra 'Italica'</i> Italian black poplar	15.0	62	1	2.4	2.6	3.0	2.5	1.5	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems.		173.9	7.4	10-20	C2
Tree T64	1	<i>Populus nigra 'Italica'</i> Italian black poplar	13.0	48	1	1.2	2.4	3.0	1.8	0.5	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems.		104.2	5.8	10-20	C2

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category	
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								Crown Clearance (m)
Tree T 65	1	<i>Populus nigra 'Italica'</i> Italian black poplar	14.0	62	1	2.4	1.5	3.0	2.5	1.5	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Access to inspect base - Restricted / obscured. Epicormic growth - Bole / principal stems.		173.9	7.4	10-20	C2
Tree T 66	1	<i>Quercus robur</i> English oak	12.0	72	1	9.7	5.8	7.4	7.8	3.0	Mature	Structural condition Fair. Physiological condition Fair. Deadwood - Major. Pollard - Regrown. Poor past pruning. Crown to ground level Deadwood present believed to not be a significant risk to targets		234.5	8.6	20-40	B2
Tree T 67	1	<i>Populus nigra 'Italica'</i> Italian black poplar	12.0	29	1	1.5	1.5	1.5	1.5	1.0	Early Mature	Structural condition Poor. Physiological condition Poor. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Decay / structural defect - Extensive. Epicormic growth - Bole / principal stems.		38.0	3.5	0-10	U
Tree T 68	1	<i>Populus nigra 'Italica'</i> Italian black poplar	15.0	60	1	2.8	2.4	3.0	1.8	2.0	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Epicormic growth - Bole / principal stems.		162.9	7.2	10-20	C2
Tree T 69	1	<i>Populus nigra 'Italica'</i> Italian black poplar	13.0	41	1	2.8	2.4	3.0	2.7	3.0	Mature	Structural condition Poor. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Pollard - Regrown. Epicormic growth - Bole / principal stems.		76.0	4.9	10-20	C2
Tree T 70	1	<i>Quercus robur</i> English oak	14.0	72	1	9.1	8.0	7.6	8.9	3.0	Mature	Structural condition Good. Physiological condition Good. Deadwood - Minor. Crown to ground level Deadwood present believed to not be a significant risk to targets		234.5	8.6	40+	A1
Tree T 71	1	<i>Populus nigra 'Italica'</i> Italian black poplar	24.0	91	1	2.8	2.4	3.0	1.8	8.0	Mature	Structural condition Fair. Physiological condition Fair. Decay / structural defect - Open cavity / cavities. Fork - Weak with included bark.		374.6	10.9	20-40	B2
Tree T 72	1	<i>Quercus robur</i> English oak	14.0	73	1	10.7	9.8	10.4	8.9	2.5	Mature	Structural condition Good. Physiological condition Fair. Deadwood - Major. Decline - Suspected. Ivy or climbing plant. Crown to ground level Deadwood present believed to not be a significant risk to targets Heavily Ivy clad stem		241.1	8.8	40+	B1
Tree T 73	1	<i>Quercus robur</i> English oak	13.0	42	1	8.0	3.2	4.4	2.6	5.0	Early Mature	Structural condition Fair. Physiological condition Fair. Deadwood - Minor. Unbalanced crown - Minor. Competition - Adjacent trees. Deadwood present believed to not be a significant risk to targets Ivy clad stem		79.8	5.0	40+	B1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS						Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)									
Tree T74	1 <i>Fraxinus excelsior</i> Ash	13.0	37	1	9.9	3.2	3.4	2.6	2.5	Early Mature	Structural condition Fair. Physiological condition Fair. Deadwood - Minor. Unbalanced crown - Minor. Competition - Adjacent trees. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Ivy clad stem		61.9	4.4	20-40	C2	
Tree T75	1 <i>Quercus robur</i> English oak	14.0	58	1	8.5	4.6	2.5	7.6	2.5	Early Mature	Structural condition Fair. Physiological condition Fair. Deadwood - Minor. Unbalanced crown - Minor. Competition - Adjacent trees. Deadwood present believed to not be a significant risk to targets Ivy clad stem		152.2	7.0	40+	B2	
Tree T76	1 <i>Fraxinus excelsior</i> Ash	15.0	80	1	8.0	4.0	4.0	4.0	1.0	Post Mature	Structural condition Poor. Physiological condition Poor. Fallen tree / trees - Partial collapse. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		289.5	9.6	0-10	U	
Hedge H77	8 <i>Sambucus nigra</i> Elder 5 <i>Fraxinus excelsior</i> Ash 25 <i>Crataegus monogyna</i> Common hawthorn	3.5	5						0.0	Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Neglected / overgrown. Height, spread, tree numbers and DBH estimated for group				10-20	C2	
Tree T78	1 <i>Fagus sylvatica</i> Beech	16.0	68	1	9.0	9.0	9.0	9.0	3.0	Mature	Structural condition Fair. Physiological condition Fair. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		209.2	8.2	40+	B1	
Group G79	25 <i>Salix caprea</i> Goat willow 15 <i>Quercus robur</i> English oak 2 <i>Populus nigra 'Italica'</i> Italian black poplar 15 <i>Fraxinus excelsior</i> Ash	8.0	10						0.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Competition - Adjacent trees. Natural regeneration. Height, spread, tree numbers and DBH estimated for group Dense group of young - semi mature understory				20-40	C3	

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS					Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T80	1 <i>Aesculus hippocastanum</i> Horse chestnut	16.0	68	1	9.0	9.0	9.0	9.0	3.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		209.2	8.2	20-40	B1
Tree T81	1 <i>Acer pseudoplatanus</i> Sycamore	15.0	52	1	9.0	9.0	9.0	9.0	3.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		122.3	6.2	40+	B1
Tree T82	1 <i>Salix fragilis</i> Crack willow	13.0	52	1	7.0	7.0	7.0	7.0	2.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		122.3	6.2	40+	B1
Group G83	6 <i>Pinus sylvestris</i> Scots pine	14.0	45						3.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Cannot access trees due to dense vegetation. Height, spread and DBH estimated for group Located on adjacent property				20-40	B2
Tree T84	1 <i>Pinus sylvestris</i> Scots pine	11.0	28	1	4.0	4.0	3.0	4.0	4.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		35.5	3.4	40+	B1
Tree T85	1 <i>Fraxinus excelsior</i> Ash	14.0	24	1	5.0	5.0	5.0	5.0	3.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		26.1	2.9	20-40	C1
Tree T86	1 <i>Fraxinus excelsior</i> Ash	16.0	34	1	7.0	7.0	7.0	7.0	3.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		52.3	4.1	10-20	C1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	Height (m)	DIMENSIONS						Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T87	1	<i>Pinus sylvestris</i> Scots pine	13.0	32	1	4.0	4.0	3.0	4.0	4.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		46.3	3.8	40+	B2
Tree T88	1	<i>Pinus sylvestris</i> Scots pine	13.0	32	1	4.0	4.0	4.0	4.0	4.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		46.3	3.8	40+	B2
Tree T89	1	<i>Fraxinus excelsior</i> Ash	14.0	22	1	5.0	5.0	5.0	5.0	3.0	Early Mature	Structural condition Good. Physiological condition Good. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Competition - Adjacent trees. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		21.9	2.6	20-40	C2
Tree T90	1	<i>Pinus sylvestris</i> Scots pine	11.0	28	1	4.0	4.0	3.0	4.0	4.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		35.5	3.4	40+	B2
Tree T91	1	<i>Pinus sylvestris</i> Scots pine	13.0	26	1	4.0	4.0	3.0	4.0	3.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		30.6	3.1	40+	B2
Tree T92	1	<i>Aesculus hippocastanum</i> Horse chestnut	16.0	54	1	8.0	6.0	4.0	3.0	3.0	Late Mature	Structural condition Poor. Physiological condition Poor. Shedding limb / limbs - Major. Access to inspect base - Not possible. Decline - Evident / observed. Base / stems obscured - Vegetation. Branch - Broken. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		131.9	6.5	10-20	C3
Tree T93	1	<i>Pinus sylvestris</i> Scots pine	14.0	31	1	4.0	4.0	3.0	4.0	5.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		43.5	3.7	40+	B2

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS					Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Group G94	15 <i>Fraxinus excelsior</i> Ash	15.0	35						2.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group Crowns touching ground Located on adjacent property				20-40	B2
Tree T95	1 <i>Populus x canadensis</i>	18.0	42	1	4.0	9.0	5.0	5.0	3.0	Mature	Structural condition Poor. Physiological condition Fair. Leaning trunk - Major. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		79.8	5.0	10-20	C3
Tree T96	1 <i>Populus x canadensis</i>	14.0	42	1	4.0	7.0	5.0	5.0	3.0	Mature	Structural condition Poor. Physiological condition Fair. Leaning trunk - Major. Decay / structural defect - Extensive. Access to inspect base - Not possible. Fallen tree / trees - Partial collapse. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		79.8	5.0	0-10	U
Tree T97	1 <i>Pinus sylvestris</i> Scots pine	13.0	26	1	4.0	4.0	3.0	4.0	3.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated		30.6	3.1	40+	B2
Tree T98	1 <i>Salix fragilis</i> Crack willow	13.0	52	1	9.0	9.0	9.0	9.0	2.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Decay / structural defect - Principal stems. Base / stems obscured - Vegetation. Located on adjacent land Dense vegetation obscuring thorough inspection Off site tree - dimensions estimated Crown to ground level		122.3	6.2	0-10	U
Tree T99	1 <i>Acer pseudoplatanus</i> Sycamore	14.0	35	1	5.0	6.0	6.0	6.0	2.0	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Ivy or climbing plant. Crown spreads estimated due to dense vegetation Heavily Ivy clad stem Located on adjacent land Unable to inspect tree(s) closely due to dense undergrowth/shrubs.		55.4	4.2	20-40	B2

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS					Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T100	1 <i>Quercus robur</i> English oak	17.0	68	1	8.0	11.0	6.0	8.0	4.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Ivy or climbing plant. Crown spreads estimated due to dense vegetation Ivy clad stem Located on adjacent land Unable to inspect tree(s) closely due to dense undergrowth/shrubs.		209.2	8.2	40+	B2
Tree T101	1 <i>Acer pseudoplatanus</i> Sycamore	17.0	24	1	4.0	4.0	4.0	4.0	4.0	Early Mature	Structural condition Good. Physiological condition Fair. Access to inspect base - Not possible. Crown difficult to assess due to dense neighbouring vegetation Crown spreads estimated due to dense vegetation Located on adjacent land		26.1	2.9	40+	B2
Tree T102	1 <i>Fagus sylvatica</i> Beech	14.0	66	1	5.1	9.6	7.7	6.4	2.5	Mature	Structural condition Good. Physiological condition Fair. Bark wound - Physical damage or vandalism. Crown to ground level		197.1	7.9	40+	B1
Tree T103	1 <i>Fagus sylvatica</i> Beech	15.0	116	1	9.3	9.1	9.4	8.9	2.0	Mature	Structural condition Fair. Physiological condition Good. Bark wound - Physical damage or vandalism. Fork - Suspected structurally sound. Deadwood - Major. Crown to ground level Deadwood present believed to not be a significant risk to targets Three stems from 3 metres		608.7	13.9	40+	A1
Tree T104	1 <i>Fagus sylvatica</i> Beech	12.0	55	1	5.8	6.9	4.8	5.7	2.5	Early Mature	Structural condition Good. Physiological condition Good. Excavation within root zone - Burrowing. Crown to ground level		136.8	6.6	40+	B1
Tree T105	1 <i>Fagus sylvatica</i> Beech	13.0	70	1	6.5	8.1	6.8	7.9	2.0	Mature	Structural condition Good. Physiological condition Good. Deadwood - Major. Crown to ground level Deadwood present believed to not be a significant risk to targets		221.7	8.4	40+	B1
Tree T106	1 <i>Fagus sylvatica</i> Beech	13.0	68	1	6.2	9.1	5.9	7.9	2.0	Mature	Structural condition Good. Physiological condition Good. Deadwood - Major. Bark wound - Physical damage or vandalism. Crown to ground level Deadwood present believed to not be a significant risk to targets		209.2	8.2	40+	B1
Tree T107	1 <i>Fagus sylvatica</i> Beech	12.0	65	1	6.9	6.4	5.9	6.8	2.5	Early Mature	Structural condition Good. Physiological condition Good. Deadwood - Major. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Crown to ground level Deadwood present believed to not be a significant risk to targets		191.1	7.8	40+	B1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS								Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T108	1	<i>Quercus robur</i> English oak	6.0	23	1	3.7	2.8	3.6	3.8	0.5	Young	Structural condition Good. Physiological condition Good. Crown to ground level		23.9	2.8	40+	B1
Tree T109	1	<i>Fagus sylvatica</i> Beech	9.0	42	1	4.6	5.6	4.1	4.5	1.5	Semi Mature	Structural condition Good. Physiological condition Good. Epicormic growth - Bole / principal stems. Crown to ground level		79.8	5.0	40+	B1
Tree T110	1	<i>Fagus sylvatica</i> Beech	8.0	39	1	5.1	5.6	4.9	4.8	1.5	Semi Mature	Structural condition Good. Physiological condition Good. Epicormic growth - Bole / principal stems. Crown to ground level		68.8	4.7	40+	B1
Tree T111	1	<i>Fagus sylvatica</i> Beech	12.0	66	1	6.6	7.3	5.9	6.8	2.0	Mature	Structural condition Good. Physiological condition Good. Deadwood - Minor. Crack - Longitudinal / shear crack. Crown to ground level Deadwood present believed to not be a significant risk to targets Cracks occluded - suspected to be caused by rapid growth, no concerns over structural integrity		197.1	7.9	40+	B1
Tree T112	1	<i>Fagus sylvatica</i> Beech	14.0	57	1	6.0	7.1	6.5	5.4	2.0	Early Mature	Structural condition Good. Physiological condition Good. Deadwood - Minor. Bark wound - Physical damage or vandalism. Crown to ground level Deadwood present believed to not be a significant risk to targets		147.0	6.8	40+	B1
Tree T113	1	<i>Fagus sylvatica</i> Beech	12.0	41	1	5.4	8.0	6.6	6.5	2.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Deadwood - Minor. Crack - Longitudinal / shear crack. Crown to ground level Deadwood present believed to not be a significant risk to targets Cracks occluded - suspected to be caused by rapid growth, no concerns over structural integrity		76.0	4.9	40+	C1
Tree T114	1	<i>Quercus robur</i> English oak	14.0	34	1	5.5	5.5	5.5	5.5	5.0	Early Mature	Structural condition Good. Physiological condition Good. Located on adjacent land Off site tree - dimensions estimated		52.3	4.1	40+	B1
Tree T115	1	<i>Fraxinus excelsior</i> Ash	14.0	31	1	5.5	5.5	5.5	5.5	5.0	Early Mature	Structural condition Good. Physiological condition Good. Located on adjacent land Off site tree - dimensions estimated		43.5	3.7	20-40	C1
Tree T116	1	<i>Quercus robur</i> English oak	12.0	49 AVE	2	4.4	6.1	6.9	7.2	0.5	Early Mature	Structural condition Poor. Physiological condition Fair. Access to inspect base - Restricted / obscured. Base / stems obscured - Vegetation. Shedding limb / limbs - Historic. Unbalanced crown - Minor. Ivy or climbing plant. Decay / structural defect - Open cavity / cavities. Heavily Ivy clad stem Decay pockets at 8 meters		139.2	6.7	20-40	C1

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS								Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)	Crown Clearance (m)							
Tree T 117	1	<i>Quercus robur</i> English oak	14.0	43	1	3.6	5.3	7.3	5.8	1.5	Early Mature	Structural condition Good. Physiological condition Good. Competition - Adjacent trees. Unbalanced crown - Minor. Crown to ground level		83.6	5.2	40+	B1
Group G 118	50 10	<i>Quercus robur</i> English oak <i>Crataegus monogyna</i> Common hawthorn	4.0	10						0.5	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Appears to be natural regeneration but almost exclusively Oak. Height, spread, tree numbers and DBH estimated for group				40+	C1
Group G 119	25 25 50 35 25 50 75	<i>Salix caprea</i> Goat willow <i>Quercus robur</i> English oak <i>Prunus spinosa</i> Blackthorn <i>Pinus sylvestris</i> Scots pine <i>Fraxinus excelsior</i> Ash <i>Crataegus monogyna</i> Common hawthorn <i>Betula pendula</i> Silver birch	10.0	15						0.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Natural regeneration. Height, spread, tree numbers and DBH estimated for group				20-40	C3
Group G 120	1 3 3	<i>Taxus baccata</i> Yew <i>Sambucus nigra</i> Elder <i>Crataegus monogyna</i> Common hawthorn	4.0	10						0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group				10-20	C3
Tree T 121	1	<i>Tilia cordata</i> Small leaved lime	17.0	49	1	5.6	5.6	5.6	5.6	3.0	Mature	Structural condition Good. Physiological condition Good. Located on adjacent land Off site tree - dimensions estimated except western crown spread		108.6	5.9	40+	B1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category	
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								Crown Clearance (m)
Tree T122	1	<i>Quercus robur</i> English oak	18.0	65	1	7.0	7.0	7.0	10.9	3.0	Mature	Structural condition Good. Physiological condition Good. Located on adjacent land Off site tree - dimensions estimated except western crown spread		191.1	7.8	40+	A1
Tree T123	1	<i>Tilia cordata</i> Small leaved lime	12.0	31	1	3.5	4.8	3.5	4.8	3.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Located on adjacent land Off site tree - dimensions estimated except western crown spread		43.5	3.7	40+	B1
Tree T124	1	<i>Quercus robur</i> English oak	18.0	72	1	9.0	9.0	9.0	11.2	3.0	Mature	Structural condition Good. Physiological condition Good. Ivy or climbing plant. Located on adjacent land Off site tree - dimensions estimated except western crown spread Ivy clad stem		234.5	8.6	40+	A1
Tree T125	1	<i>Tilia cordata</i> Small leaved lime	16.0	34	1	4.0	5.8	4.0	5.8	3.0	Semi Mature	Structural condition Good. Physiological condition Fair. Located on adjacent land Off site tree - dimensions estimated except western crown spread		52.3	4.1	40+	B1
Tree T126	1	<i>Quercus robur</i> English oak	14.0	48	1	5.2	5.8	6.3	10.7	2.5	Early Mature	Structural condition Fair. Physiological condition Good. Unbalanced crown - Minor. Deadwood - Major. Located on adjacent land Off site tree - dimensions estimated except western crown spread		104.2	5.8	40+	B1
Tree T127	1	<i>Tilia cordata</i> Small leaved lime	16.0	36	1	5.5	6.0	6.0	6.7	3.5	Early Mature	Structural condition Good. Physiological condition Fair. Located on adjacent land Off site tree - dimensions estimated except western crown spread		58.6	4.3	40+	B1
Tree T128	1	<i>Quercus robur</i> English oak	18.0	65	1	7.0	7.0	7.0	8.5	3.0	Mature	Structural condition Good. Physiological condition Fair. Located on adjacent land Off site tree - dimensions estimated except western crown spread		191.1	7.8	40+	B1
Tree T129	1	<i>Pinus sylvestris</i> Scots pine	9.0	25	1	1.5	1.0	3.0	3.0	3.0	Semi Mature	Structural condition Fair. Physiological condition Poor. Decline - Evident / observed. Located on adjacent land Off site tree - dimensions estimated except southern crown spread		28.3	3.0	0-10	U
Tree T130	1	<i>Fagus sylvatica</i> Beech	12.0	25 AVE	2	2.0	4.5	7.1	4.5	3.0	Early Mature	Structural condition Fair. Physiological condition Fair. Stems - Co-dominant. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Located on adjacent land Off site tree - dimensions estimated except southern crown spread		50.2	4.0	10-20	C2

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees Species	Height (m)	Stem diameter (cm)	DIMENSIONS					Crown Clearance (m)	Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
				No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								
Tree T 131	1 <i>Populus nigra 'Italica'</i> Italian black poplar	22.0	48	1	3.0	3.0	3.0	3.0	10.0	Mature	Structural condition Poor. Physiological condition Fair. Leaning trunk - Major. Access to inspect base - Restricted / obscured. Ivy or climbing plant. Located on adjacent land Off site tree - dimensions estimated Heavily Ivy clad stem		104.2	5.8	10-20	C3
Group G 132	3 <i>Sambucus nigra</i> Elder 9 <i>Quercus robur</i> English oak 2 <i>Malus sylvestris</i> Crab apple 5 <i>Crataegus monogyna</i> Common hawthorn	6.0	18						0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group				10-20	C3
Group G 133	3 <i>Populus x canadensis</i> 1 <i>Fagus sylvatica</i> Beech 2 <i>Acer pseudoplatanus</i> Sycamore	26.0	65						2.0	Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Base / stems obscured - Vegetation. Height, spread, tree numbers and DBH estimated for group Cannot accurately plot stem positions, all within 1 metre of boundary Located on adjacent property				20-40	B2
Tree T 134	1 <i>Crataegus monogyna</i> Common hawthorn	6.0	9 AVE	6	2.0	2.6	3.1	2.8	1.0	Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Crown to ground level		22.0	2.6	10-20	C3
Tree T 135	1 <i>Crataegus monogyna</i> Common hawthorn	4.0	6 AVE	6	3.0	2.8	3.1	2.8	0.0	Early Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Crown to ground level		9.8	1.8	10-20	C3
Tree T 136	1 <i>Acer pseudoplatanus</i> Sycamore	10.0	22	1	4.0	4.0	5.3	4.0	4.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Located on adjacent land Off site tree - dimensions estimated except southern crown spread		21.9	2.6	40+	C2
Group G 137	1 <i>Malus sylvestris</i> Crab apple	7.0	28	1	4.0	4.0	4.6	4.0	2.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Located on adjacent land Off site tree - dimensions estimated except southern crown spread Heavily Ivy clad stem		35.5	3.4	10-20	C2

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category	
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								Crown Clearance (m)
Tree T 138	1	<i>Quercus robur</i> English oak	4.0	9	1	2.6	2.6	2.8	2.4	0.5	Young	Structural condition Good. Physiological condition Good. Crown to ground level		3.7	1.1	40+	C1
Tree T 139	1	<i>Quercus robur</i> English oak	5.0	12	1	3.2	3.0	3.4	3.1	0.5	Young	Structural condition Good. Physiological condition Good. Crown to ground level		6.5	1.4	40+	C1
Tree T 140	1	<i>Crataegus monogyna</i> Common hawthorn	7.0	11 AVE	7	4.0	4.0	4.0	4.0	0.0	Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Access to inspect base - Not possible. Crown to ground level Crown spreads estimated due to dense vegetation Dense vegetation obscuring thorough inspection		38.3	3.5	20-40	C1
Tree T 141	1	<i>Quercus robur</i> English oak	5.0	12	1	2.8	2.8	2.8	2.8	0.5	Young	Structural condition Good. Physiological condition Good. Access to inspect base - Not possible. Crown to ground level Crown spreads estimated due to dense vegetation		6.5	1.4	40+	C1
Group G 142	3	<i>Sambucus nigra</i> Elder	6.0	8	1	2.8	2.8	2.8	2.8	0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group			10-20	C3	
4	<i>Quercus robur</i> English oak																
1	<i>Malus sylvestris</i> Crab apple																
10	<i>Crataegus monogyna</i> Common hawthorn																
Group G 143	5	<i>Salix fragilis</i> Crack willow	12.0	24						0.0	Early Mature	Structural condition Fair. Physiological condition Fair. Access to inspect base - Not possible. Height, spread, tree numbers and DBH estimated for group Dense scrub and vegetation limits access			20-40	C3	
15	<i>Quercus robur</i> English oak																
5	<i>Fraxinus excelsior</i> Ash																
30	<i>Crataegus monogyna</i> Common hawthorn																
5	<i>Acer pseudoplatanus</i> Sycamore																

Stem **green** estimated value

Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category	
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)								Crown Clearance (m)
Tree T144	1	<i>Crataegus monogyna</i> Common hawthorn	7.0	11 AVE	7	4.0	4.0	4.0	4.0	0.0	Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Access to inspect base - Not possible. Crown to ground level Crown spreads estimated due to dense vegetation Dense vegetation obscuring thorough inspection		38.3	3.5	20-40	C1
Tree T145	1	<i>Crataegus monogyna</i> Common hawthorn	7.0	11 AVE	7	4.0	4.0	4.0	4.0	0.0	Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Access to inspect base - Not possible. Crown to ground level Crown spreads estimated due to dense vegetation Dense vegetation obscuring thorough inspection		38.3	3.5	20-40	C1
Tree T146	1	<i>Crataegus monogyna</i> Common hawthorn	7.0	11 AVE	7	4.0	4.0	4.0	4.0	0.0	Mature	Structural condition Good. Physiological condition Good. Multi-stemmed. Access to inspect base - Not possible. Crown to ground level Crown spreads estimated due to dense vegetation Dense vegetation obscuring thorough inspection		38.3	3.5	20-40	C1
Tree T147	1	<i>Quercus robur</i> English oak	3.5	11	1	4.0	2.9	3.4	2.8	0.5	Young	Structural condition Good. Physiological condition Good. Crown to ground level		5.5	1.3	40+	C1
Tree T148	1	<i>Quercus robur</i> English oak	4.0	8 AVE	2	3.5	3.5	3.5	3.5	0.5	Young	Structural condition Good. Physiological condition Good. Crown to ground level		5.1	1.3	40+	C1
Hedge H149	52	<i>Crataegus monogyna</i> Common hawthorn	1.5	5						0.0	Semi Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Maintained. Height, spread, tree numbers and DBH estimated for group Located on adjacent property				20-40	C2
Group G150	26	<i>Quercus robur</i> English oak	6.0	9						1.0	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Height, spread, tree numbers and DBH estimated for group Mostly open grown, young Oak trees				40+	C1
Group G151	50 5	<i>Quercus robur</i> English oak <i>Crataegus monogyna</i> Common hawthorn	6.0	9						1.0	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Height, spread, tree numbers and DBH estimated for group Mostly open grown, young Oak trees				40+	C1
Group G152	45	<i>Quercus robur</i> English oak	6.0	9						1.0	Young	Structural condition Good. Physiological condition Good. Young planted tree / trees. Height, spread, tree numbers and DBH estimated for group Mostly open grown, young Oak trees				40+	C1

Stem **green** estimated value
Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Ashbourne Playing Field, Mangrove Road, Hertford, SG13 8AL

Tree/Group Number	No. of Trees	Species	DIMENSIONS							Life stage	Condition Notes	Recommendations	RPA (m ²)	RPR (m)	Life expectancy (yrs)	BS Category
			Height (m)	Stem diameter (cm)	No. of Stems	Spread N (m)	Spread E (m)	Spread S (m)	Spread W (m)							
Group G 153	100	<i>Quercus robur</i> English oak	5.0	8						0.5	Young	Structural condition Fair. Physiological condition Fair. Natural regeneration. Competition - Adjacent trees. Height, spread, tree numbers and DBH estimated for group			20-40	C2
	30	<i>Crataegus monogyna</i> Common hawthorn										Dense understory vegetation.				
	20	<i>Betula pendula</i> Silver birch														
	20	<i>Acer campestre</i> Field maple														
Tree T 154	1	<i>Malus x purpurea</i> Purple Crab	6.0	18	1	2.6	1.5	2.4	3.1	2.0	Early Mature	Structural condition Fair. Physiological condition Fair. Crown reduction - Historic. Competition - Adjacent trees. Located on adjacent land	14.7	2.2	10-20	C1
Tree T 155	1	<i>Betula pendula</i> Silver birch	6.0	36	1	3.6	1.9	2.9	3.1	2.0	Mature	Structural condition Fair. Physiological condition Fair. Crown reduction - Historic. Competition - Adjacent trees. Located on adjacent land	58.6	4.3	10-20	C1
Tree T 156	1	<i>Cerasus subhirtella</i> Autumn Cherry	6.0	27	1	3.5	3.4	2.4	1.7	1.0	Mature	Structural condition Fair. Physiological condition Fair. Crown reduction - Historic. Competition - Adjacent trees. Located on adjacent land	33.0	3.2	10-20	C1
Hedge H 157	25	<i>x Cupressocyparis leylandii</i> Leyland Cypress	2.8	5							Semi Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Maintained. Height, spread, tree numbers and DBH estimated for group			20-40	C2
	25	<i>Thuja plicata</i> Western red cedar										Located on adjacent property				
Hedge H 158	20	<i>Crataegus monogyna</i> Common hawthorn	2.0	5							Semi Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Maintained. Height, spread, tree numbers and DBH estimated for group			20-40	C2
												Located on adjacent property				
Hedge H 159	8	<i>Ulmus sp.</i> Elm sp.	4.0	15							Early Mature	Structural condition Fair. Physiological condition Fair. Hedgerow - Maintained. Height, spread, tree numbers and DBH estimated for group			20-40	B2
	5	<i>Tilia cordata</i> Small leaved lime										Located on adjacent property / ownership ambiguous				
	12	<i>Laurocerasus officinalis</i> Cherry Laurel														

Stem **green** estimated value
 Stem **AVE** average stem diameter for multi-stemmed trees

The survey information in this schedule has been gathered following a BS5837 survey for planning purposes. Where hazardous trees have been noted recommendations for works may have been made but this survey cannot be relied upon as a full health and safety assessment of the trees.

Table 1 of BS5837 (2012) Cascade chart for tree quality assessment

Category and definition	Criteria (including subcategories where appropriate)			Identification on plan			
Trees unsuitable for retention (see note)							
<p>Category U</p> <p>Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years</p>	<ul style="list-style-type: none"> * Trees that have a serious, irremediable, structural defect, such that their early loss is expected due to collapse, including those that will become unviable after removal of other category U trees (e.g. where, for whatever reason, the loss of companion shelter cannot be mitigated by pruning) * Trees that are dead or are showing signs of significant, immediate, and irreversible overall decline * Trees infected with pathogens of significance to health and/or safety of other trees nearby, or very low quality trees suppressing adjacent trees of better quality <p><i>NOTE Category U trees can have existing or potential conservation value which it might be desirable to preserve; see 4.5.7</i></p>			RED			
<table border="0" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 33%; text-align: center;">1 Mainly arboricultural qualities</td> <td style="width: 33%; text-align: center;">2 Mainly landscape qualities</td> <td style="width: 33%; text-align: center;">3 Mainly cultural values, including conservation</td> </tr> </table>					1 Mainly arboricultural qualities	2 Mainly landscape qualities	3 Mainly cultural values, including conservation
1 Mainly arboricultural qualities	2 Mainly landscape qualities	3 Mainly cultural values, including conservation					
Trees to be considered for retention							
<p>Category A</p> <p>Trees of high quality with an estimated remaining life expectancy of at least 40 years</p>	<p>Tree that are particularly good examples of their species, especially if rare or unusual; or those that are essential components of groups or formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue)</p>	<p>Trees, groups or woodlands of particular visual importance as arboricultural and/or landscape features</p>	<p>Trees, groups or woodlands of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)</p>	GREEN			
<p>Category B</p> <p>Trees of moderate quality with an estimated remaining life expectancy of at least 20 years</p>	<p>Trees that might be included in category A, but are downgraded because of impaired condition (e.g. presence of significant though remediable defects, including unsympathetic past management and storm damage), such that they are unlikely to be suitable for retention for beyond 40 years; or trees lacking the special quality necessary to merit the category A designation</p>	<p>Trees present in numbers, usually growing as groups or woodlands, such that they attract a higher collective rating than they might as individuals; or trees occurring as collectives but situated so as to make little visual contribution to the wider locality</p>	<p>Trees with material conservation or other cultural value</p>	BLUE			
<p>Category C</p> <p>Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150 mm</p>	<p>Unremarkable trees of very limited merit or such impaired condition that they do not qualify in higher categories</p>	<p>Trees present in groups or woodlands, but without this conferring on them significantly greater collective landscape value; and/or trees offering low or only temporary/transient landscape benefits</p>	<p>Trees with no material conservation or other cultural value</p>	GREY			